United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

		9)	
Re-issued on July 8,	2008 to supersede the original STC,	which has been lost or misplac	eed or destroyed.
	Number		
This Certificate issued to	GATX/Airlog P.O. Box 3529 Albany, Georgia 31	706	
certifies that the change in th	le type design for the fo	llowing product/with	the limitations and
conditions therefor as specific	ed hereon meets the airc	vorthineps regisiremet	nts of hart 25 of the Federal
Aviation regulations			
			STC Surrender processed:
Original Product - Type Co	(20WE	Approval by:
	Make N B	deing	Meivin Taylor, ATL ACO Manager
	Model:	47-122	Date: 7/8/08
Description of Type Design	Change: Structura	Modification to	stretched aft upper deck
in accordance with Luca	s Aviation Inc. doc	umentation:	
Index ListMaster Drawing List	A58-3 Rev. N R56-2 Rev. A	· ·	/94 /94
	\wedge		
Or later FAA approved r	ewisions.	• .	
Limitations and Condition certificated product of incorporated puless it	this model on which	n other approved .	nship between this change
and any of those previous effect upon the airwort	hiness of the certi	ficated product. 9757, 19753 and 1	This approval is limited 9754. The applicability
	tead to those altera	II WIIIIIIII IIAVE DEG	II COIIVCE EEG
			C No. SA1955CE-D and have this STC must be included
in the permanent record	ls of the modified a	ircraft.	
This certificate and the supp	- tien data which is the	la harir lor anneovat	shall remain in effect until
This sertificate and the supp	l Lee a termination o	lata is athennisa estat	blished by the Administrator
		use is tracertired touch	and the signal and th
of the Federal Aviation A	Odministration.		·
Date of application: Janu	ary 24, 1994	Date reissued: M	arch 17, 1995
Date of issuance: March 3		Date amended :	
,			
		By direction of the	a. Administrator
ERAL AL	4	No to	1 Am Phone
	Q Q	(Sign	ature)
	- *	Natalie Phan-Tr	an
18	'	Agting Manager	rechnical & Admin.

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Support Staff, ANM-103L